

**POWDER METALLURGY
KEYS**

I Choose the correct alternative:

1. A
2. A
3. A
4. D
5. B
6. A
7. B
8. D
9. B
10. C

II Fill in the blanks

11. Free energy reductions
12. Mg, Si or Cu
13. Low hysteresis loss
14. Powder or Sinter forging
15. Nickel Base alloys
16. SmCo_5
17. Tungsten and molybdenum
18. 15 – 30 %
19. Precipitation
20. Cemented carbides